OIL & NATURAL GAS CORPORATION
(W.O.U.) KARMACHARI SANGHATANA

AFFILIATED TO - PETROLIUM & GAS WORKERS' FEDERATION OF INDIA

Reg. No. (By - II - 8268) Tel. : 022-26274102

Flat No.102, 1st Floor, Acme Hormony-I, Poonam Nagar, Off. JV Link Road, Andheri (E), Mumbai - 400 093.

Website : www.ksmumbai.com

REF. : ONGC/KS/ 118 /2026 DATE : 04/11/2026

To,

The ED- MH Asset,
ONGC-WOU,
Vasudhara Bhavan,
Bandra (E),
Mumbai- 400 051

Subject: Urgent Intervention Regarding Critical Maintenance, Equipment Reliability & Safety Concerns At NQO Process Complex.

Respected Sir,

We are in receipt of letter from crew member of NQO Process platform, dated 31.10.2026 from its Offshore Secretary at NQO Process Platform highlighting longstanding maintenance deficiencies & potential safety hazards across the NQO Process Complex. We consider these matters serious, as they directly concern personnel safety, asset integrity & continuity of offshore operations.

1. **NQO CT Pump:** Mechanical seal leakage: Recurring oil leakage reportedly continues without permanent rectification. We request an immediate technical inspection, root-cause analysis & lasting repair, with appropriate interim safeguards.

2. **NQP Utility Pump:** Non-operational condition: The pump has reportedly remained out of service for several months. The NQG utility pump is also reported to be operating below full capacity. Both systems require priority assessment & restoration of dependable utility & backup arrangements.

3. **NLRNC Project:** Valve deficiencies: Several valves are reported to be partially functional or passing. A comprehensive valve-wise inspection, functional testing & corrective programme should be undertaken to ensure reliable process control & isolation.

4. **Damaged Chequered Deck Plates:** Damaged plates across the Process Complex present slip, trip & fall hazards. We request an immediate area-wise survey, barricading of unsafe locations & replacement of damaged plates on priority.

5. **NQD Platform:** 90 kg/cm² gas header: The reported deterioration of this high-pressure header warrants urgent integrity assessment by competent specialists, necessary risk mitigation & repair or replacement as dictated by inspection findings.

Contd....2

6. NQD Platform: Access bridge: The reportedly poor condition of the bridge connecting NQD Platform calls for prompt structural assessment, safe-access controls & time-bound rehabilitation.

We requests Management to arrange a joint site inspection involving Operations, Maintenance, HSE & employee representatives; classify immediate hazards; & communicate a written, item-wise action plan with responsible officers & completion dates. Pending permanent rectification, suitable interim safety measures must be enforced.

Thanking you,
Yours faithfully,

(Pradeep Mayekar)
General Secretary

Copy to:

1. GGM (Prod.), Head Offshore Safety, ONGC-WOU,V. Bhavan,Bandra (E),Mum- 51
2. SM- MH Asset, ONGC-WOU,MH Asset,Vasudhara Bhavan,Bandra (E),Mum.- 51
3. SAM- NQO, ONGC-WOU,MH Asset,Vasudhara Bhavan,Bandra (E), Mumbai- 51
4. GM, I/c-HR/ER,MH Asset, ONGC-WOU,Vasudhara Bhavan,Bandra (E),Mum-51
5. GM I/c-IR, ONGC-WOU, NBP Gr.Heights, BKC, Bandra (E), Mumbai – 51.