

## OIL & NATURAL GAS COMMISSION (B.O.P.) KARMACHARI SANGHATANA

AFFILIATED TO - PETROLIUM & GAS WORKERS' FEDERATION OF INDIA

Reg. No. (By - II - 8268)

Tel.: 2659 9775

Flat No.102, 1st Floor, Acme Hormony-I, Poonam Nagar, Off. JV Link Road, Andheri (E), Mumbai - 400 093.

DATE: 19,03.2013

REF.: ONGC/KS/ 43/2013

To,
The ED, MH Asset,
ONGC, WOU,
Vasudhara Bhavan, 8th Floor,
Bandra (E),
Mumbai 400051.

Subject: Non availability of hot water in NQO platform for more than seven months.

Respected Sir,

Negative thought of the day, "seeking interaction is viewed as being encountered" some officers, surprisingly even at the level of GM still continue to have such outlook about the Unions, and do not stop commenting, least concerned about any extremes.

After having failed to yield a result through repeated interaction with OIM and MM in NQO Platform for the past six months who have their limitations, our committee has raised their level of surfacing the factual, hopping to see the other side of the tunnel, but have unfortunately encountered a road block of **arrogance and high handedness**.

We have been educating our members not to rush to the union for every small reason, any installation in offshore, be it Rig or Production Platform is a family in itself, and all problems possibly, should be resolved within its boundaries to cultivate amicable and healthy atmosphere.

We need not explain to your authority how inconvenient it is when hot water is not available, and a seven months stretch, you will agree with us is asking too much and then face misunderstanding, misquoting and arrogance or high handedness of officers who are only trying to blanket their failure in getting the problem solved.

Before directing our boys to proceed on any action program like "Hunger Strike" we thought it would be appropriate on our part to bring to your notice about the plight of all officials working in NQO Platform. We envisage the delay in repairing the heaters could be non availability of spare parts or acquiring substandard material (Coils) which do not withstand the load, both the subjects are chronic yet remain unaddressed.

We wish and request your esteemed authority to have a personal over view of the situation and take corrective action before patience breaks its boundaries. At the same time we also request you kindly put across the perception to some of our officers that we are ONGCians engaged in joint ventures for maintaining production levels, and not enemies at war raising our temperatures. Please do not take this as allegation, but we are certainly hurt by some remarks, all we want is an early repair of all the four heaters.

Thanking you, Yours faithfully,

(Pradeep Mayekar) General Secretary

## Copy to:

≻1. ED - HRO, ONGC, WOU, NSE, Bandra (E), Mumbai.

2. GGM - SM, MH- Asset, V. Bhavan, Bandra (E), Mumbai.

3. GM - I/c HR-ER, MH Asset, V. Bhavan, Bandra (E), Mumbai.

4. Area Manager, (N), MH- Asset, V. Bhavan, Bandra (E), Mumbai.

5. Location Manager, NQO, V. Bhavan, Bandra (E), Mumbai.

6. DGM - I/c HR-IR, ONGC, WOU, NSE, Bandra (E), Mumbai.

7. OIM, NQO Platform, MH Asset, Mumbai High, Mumbai.